
MT600
when ¼ jack inserted, MT600 signal doesn't go to filter anymore
1M
500K lin
yellow purple yellow
pin 7 LED
Brown blk yellow
22µF
1500pF
.1µF
22pF
470pF
green brown orange
yellow purple orange
1µF
cut trace
cut trace
cut trace
from MP signal in
MN Chorus chip
red blk orange
50K
Yellow Purple Red
100K
3363 cutoff res
3364 angle
3365 back & vctln
removed
keyside